RA Bill no I[st] & final

008-14-0000247

M.A.R. 57 (Rule 116)

Measurement Book

No. A/10 187530

Serial No. BR-239/31-7-14

Name of work Cleaning to road and drain From at Munnekolalu layout in ward no-8 Kadugodi Sub division

Name of Contractor of nature of Agency KRIDL

Date of commencement of work Work order No. EE/BTP/KRIDL/W0/432/2013-14 dt 21/2/2014

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	① Lead not exceeding by manual means in hard soil involving an average horizontal throw upto 100 mts etc complete.						
	Desilting of drain						
	8th main road RHS	1	30.00	0.45	0.45	6.08 cum	
		1	30.00	0.45	0.45	4.73 "	
		1	30.00	0.45	0.20	2.70 "	
		1	30.00	0.45	0.30	4.05 "	
		1	30.00	0.45	0.25	3.38 "	
		1	30.00	0.45	0.45	6.08 "	
	8th main road LHS	1	6.30	0.45	0.20	0.57 "	
		1	30.00	0.45	0.45	6.08 "	
		1	30.00	0.45	0.25	3.38 "	

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
			KRIDE Service Charge @ 11%.				R 98119.00
			Third party Admin Charge @ 1%				R 8920.00
			checked & found all items are correct D. Mandla Mudau			Total R 9,99,033.00 7/7	988128.00
			Mpumalanga Langa				
			Mpumalanga Langa Road				
							ASHPACT
							CULVERT

M.A.R. 57 (Rule 116)

Measurement Book

No. A/10

187535

Serial No.....

Name of work.....From.....To.....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measuremer
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	988128=00 143293=00 844835=00			IT — 19763 — VAT — 39525 — Fee — 54343 — Cess — 9881 — Cess — 18789 — Roy — 500 — 143293=00			